



Leakage Investigation Survey

Client: Car dealership, Glasgow

Mains water meter information

Size (mm)	15-28	✓	32-50		75-100		125-200		Above 200mm	
Serial number	16N124358									
Readings (1)	19235.330				Time:	09.03 8 th November 2018				
Readings (2)	19235.530				Time:	09.08 8 th November 2018				
Location	Meter located in footpath left of entrance road									

Leakage Activities

Acoustic sounding	✓	Correlation		Ground microphone	✓	Environmental Inspection	
Other	Isolation of rising main						
Pipe traced		CAT & Genny			Distance		
Pipe correlated	Accelerometer			Hydrophones	Distance		

Background Information

Suspected water leak causing high water bills in excess of £20,000pa.

Activity Summary

Pipework & Metering

The water meter is located in footpath, LHS of entrance road



Pic 1



Pic 2



Pic 3



Pic 4



Pic 5



Pic 6



Pic 7



Pic 8

Leakage Survey Activities

After walking the site with site manager to establish where all mains water isolation points were, the task of looking for a problem began.

A reading of the revenue meter was taken (pic 1) which had a flow rate of 2.5m³ Pper hour, on inspection of some of the internal meters it was evident that in the valeting plant room there was a sub meter (pic 3,4&5) that had a costant flow. On timing this flow rate for a while it was noted that it had a constant flow rate of 40 litres per minutes which equates to 2.4m³ per hour and 57.6m³ per day at a cost of £129 per day, this supply was then isolated.

The revenue meter was then checked and the flow rate had reduced to 0.5m³ PH (pic 2), this flow rate was confirmed by the tanks filling for the vehicle jet wash area in valeting and also the use of the jet wash.

The sub meter in the valeting plant room (pic 3) was then put back in commission, our engineer made an enquiry to the valeting manager who pointed out that the meter measured water used on the main pitch areas around the show room.

He escorted our engineer around and pointed out the standpipes around the site.

Once sounding began on the standpipes, leak noise could be heard almost straight away, on one of the standpipes, also subsidence was apparent. On checking out the standpipe a substantial leak noise could be heard, on probing of the grassed area clear water was being drawn up confirming a leak below ground at this location (pic 6,7&8).

The site is less that one year old so it maybe a warranty issue with the builder, this to be confirmed with site before action is taken.

Summary & Recommendations

Summary:

Substantial leak located on pitch standpipe

Recommendations:

Excavate and repair.

Survey carried out by

Engineer	H2O Building Services	Date	9 th November 2018
----------	-----------------------	------	-------------------------------